DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION ACTIVITY REPORT: Self Initiated Inspection

FACILITY: RIVERSIDE - CUSTER 7 CPF		SRN / ID: N7592
LOCATION: 3996 DB Trail, CUSTER TWP		DISTRICT: Cadillac
CITY: CUSTER TWP		COUNTY: ANTRIM
CONTACT:		ACTIVITY DATE: 10/26/2017
STAFF: Rob Dickman	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Inspection of this c	pt out source to obtain an accurate inventory of equipm	nent on site.
RESOLVED COMPLAINTS:		

Performed an on site inspection of this source. The purpose of this inspection was to get an accurate inventory of the permitted equipment on site.

A list of equipment on site includes:

One V-12 Caterpillar Engine, Model 3512LE, uncontrolled, Skid NGCS 192 One V-16 Caterpillar Engine, Model 3516LE, uncontrolled, Skid NGCS 191 One 400 bbl AST One electric booster compressor, not in operation at the time of inspection One glycol dehy

A review of the permit lists an additional 3516LE and a 3408TA. These engines were never installed at the facility. Riverside, while not required to, was asked to amend their permitting to reflect the equipment op-site. No further action is recommended.

NAME

DATE 11/9/17

SUPERVISOR