## DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

**ACTIVITY REPORT: Scheduled Inspection** 

N781939287		• • • • • • • • • • • • • • • • • • • •		
FACILITY: TRENDWELL ENERGY CORP- Avery 16 Booster		SRN / ID: N7819		
LOCATION: AVERY16 NW SE SE SEC 16 T30N R7E, AVERY TWP		DISTRICT: Gaylord		
CITY: AVERY TWP		COUNTY: MONTMORENCY		
CONTACT:		ACTIVITY DATE: 03/30/2017		
STAFF: Bill Rogers	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR		
SUBJECT: Minor source insp	ection			
RESOLVED COMPLAINTS:				

On March 30, 2017, I went to the site of the Avery 16 booster. It was still in our database as operating, but the permit had been voided.

There is no equipment at the site. Ther permanently closed.	efore voiding the permit was	correct. I have	changed facility status	to
NAME William J Rogers In	DATE 4/5/2017	SUPERVISOR	5N	