DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

FCE Summary Report

Facility: RIVERSIDE - NORTH BAY CPF	SRN:	N8181		
Location: T28N-R7E, SE SW SW OF SEC 6	District :	Gaylord		
	County:	ALCONA		
• • • • • • • • • • • • • • • • • • •	ompliance atus :	Compliance		
Source Class: SM OPT OUT Staff: Sharon LeBlanc				
Source Class: SM OPT OUT	Staff: Sharon	LeBlanc		
FCE Begin Date : 11/1/2021	Staff : Sharon FCE Completion Date :	11/14/2022		

List of Partial Compliance Evaluations:

Activity Date	Activity Type	Compliance Status	Comments
11/14/2022	On-site Inspection	Compliance	FY 2023 site inspection and data review- sgl
04/05/2022	MAERS	Compliance	2021 MAERS,Facility uses manufacturers and MAERS EFs to determine annual emissions for the site.Data is consistent with the previous years submittal. sgl

Wame: 19 1 Lebluc Date: 2-8-23 Supervisor: Thank Mixon

Page 1 of 1