DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION ACTIVITY REPORT: Scheduled Inspection

FACILITY: LINN Operating INC - Unit 154 Booster (Loud Twp)		SRN / ID: N8216
LOCATION: NW 1/4 NW 1/4 SEC 23 T29N R03E, LOUD TWP		DISTRICT: Gaylord
CITY: LOUD TWP		COUNTY: MONTMORENCY
CONTACT: Diane Lundin, Senior EHS Representative		ACTIVITY DATE: 04/02/2015
STAFF: Becky Radulski	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: scheduled inspectio	n	
RESOLVED COMPLAINTS:		

On April 2, 2015 traveled to N8216 Linn Energy Unit 154 located in Loud Township, Montmorency County for a scheduled inspection to determine compliance with PTI 399-08. Gloria Torello and Becky Radulski, AQD, were present for the inspection. This is a minor source.

DEQ Inspection brochures have been previously emailed to Linn Energy.

LOCATION

..........

Linn Unit 154 is located in Section 23 (T29N R3E) of Loud Township, Montmorency County. The facility is located on the south side of County Road 612, approximately 1 mile west of M-33. A map has been attached to the inside of the permit file.

EQUIPMENT ON SITE

The facility has 1 compressor building with a Caterpillar 3408 TA engine, 400 hp.

PTI 399-08 is for 1 booster engine with no control. This is only a booster with no storage tanks or glycol dehydrator on site. The natural gas is from Antrim wells.

REGULATORY DISCUSSION

The engine is subject to 40 CFR Part 63, Subpart ZZZZ, which has not been delegated to MDEQ from EPA.

INSPECTION NOTES

The site consists of a small building for the compressor engine. The engine was operating. No VE or odors present. No control but there was a muffler.

Inside was a Caterpillar 3408, which was operating at 1688 RPM. There were also several small tanks, with used oil, engine oil and small engine oil, contained.

MAERS

MAERS is not required for this minor source.

COMPLIANCE DETERMINATION

Based on the scheduled inspection, the facility appears to be in compliance with PTI 399-08. Records will be reviewed separately.

NAME Becky Radulski

DATE 4 15 15

SUPERVISOR