

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Self Initiated Inspection

N827540270

FACILITY: TUSCOLA ENERGY INC. - M & D DOWNING 2-29		SRN / ID: N8275
LOCATION: 5460 Elmwood Rd, AKRON		DISTRICT: Saginaw Bay
CITY: AKRON		COUNTY: TUSCOLA
CONTACT: Jeff Adler , President		ACTIVITY DATE: 05/09/2017
STAFF: Benjamin Witkopp	COMPLIANCE STATUS: Non Compliance	SOURCE CLASS: MINOR
SUBJECT: Follow up Site inspection of M & D 2-29 no records review		
RESOLVED COMPLAINTS:		

Andrew Kent and Ben Witkopp of the Michigan Department of Environmental Quality - Oil Gas and Minerals & Air Quality Divisions(OGMD & AQD) respectively, visited the crude oil production facility. Previously, on 4-21-17 the 2-29 tanks thief hatch was found moving up and down allowing the release of unburned hydrogen sulfide. Though the hatch was not visibly moving this time, vapor distortions were seen coming from the hatch.

On May 10 Andrew sent an email to Jeff Adler concerning the odors. Jeff responded by stating Mo Aiken said things were fine.

NAME *B. Witkopp* DATE 2-12-18 SUPERVISOR *C. Aiken*