## DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION

**ACTIVITY REPORT: Scheduled Inspection** 

N833847640

FACILITY: Battery Solutions Recovery LLC		SRN / ID: N8338		
LOCATION: 7266 KENSINGTON RD, BRIGHTON		DISTRICT: Lansing		
CITY: BRIGHTON		COUNTY: LIVINGSTON		
CONTACT: Adam Hancock , Operations Manager		ACTIVITY DATE: 01/17/2019		
STAFF: Samantha Braman	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR		
SUBJECT: Unannounced, scheduled inspection for compliance with PTI 248-09a.				
RESOLVED COMPLAINTS:				

Dan McGeen and I arrived on site at 11:40am. There were cars in the parking lot but there was no one inside the office. We drove around to the back of the building and entered through the back door. The building was empty except for one last piece of machinery, which was being moved that day. Adam Hancock, Operations Manager, was there and notified us that they were moving their facility to be joined with their Wixom facility in SE Michigan. Adam assured us that they were already in touch with the DEQ SE District and have a PTI application in. We left the facility at 12:15pm.

I will be requesting that PTI 248-09A be vo			
NAME Sauce Stree Drawen	DATE 2/4/19	SUPERVISOR	
ALOVIE CONTRACTOR	DATE	001 EI(VI00I(	