## DEPARTMENT OF ENVIRONMENTAL QUALITY

## AIR QUALITY DIVISION

## FCE Summary Report

Facility : Wolverine Power Supply Co-op - Alpine Power Plan	Wolverine Power Supply Co-op - Alpine Power Plant SRN :		
Location : 7432 M-32 Highway	District :	Gaylord	
	County :	OTSEGO	
• • • • • • • • • • • • • • • • • • • •	mpliance itus :	Compliance	
Source Class : MAJOR Staff : Bill Rogers			
	CE Completion	2/21/2019	
Comments : Inspection and record review as scheduled.			

## List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments	
02/21/2019	Scheduled Inspection	Compliance	Scheduled inspection and records review.	
01/25/2019	ROP Tech Review Notes	Compliance		
12/21/2018	ROP R215 Notification	Compliance	Establishing Responsible Official as: Mr. Dan Calverlley, Vice President effective January 1, 2019	
09/13/2018	Stack Test	Compliance	NOx Test Report. Both units passed all their NOx limits.	
07/25/2018	Stack Test Observation	Compliance	Stack test observation	
03/09/2018	MAERS	Compliance	2017 MAERS, Check MAERS for any review comments	

Name: Within Skogen Date: 2/28/2019 Supervisor:

Page 1 of 1