

DEPARTMENT OF ENVIRONMENTAL QUALITY
 AIR QUALITY DIVISION
 ACTIVITY REPORT: Self Initiated Inspection

P076037454


| | | |
|---|-------------------------------|---------------------------|
| FACILITY: Stephenson Marketing Association | | SRN / ID: P0760 |
| LOCATION: W505 South Drive, MENOMINEE | | DISTRICT: Upper Peninsula |
| CITY: MENOMINEE | | COUNTY: MENOMINEE |
| CONTACT: BILL WILSON , FEED DEPARTMENT HEAD | | ACTIVITY DATE: 10/24/2016 |
| STAFF: Joel Asher | COMPLIANCE STATUS: Compliance | SOURCE CLASS: |
| SUBJECT: Follow up on old PTI. | | |
| RESOLVED COMPLAINTS: | | |

On 6/9/1975 PTI #457-74 was issued to Stephenson Marketing Association for a feed hammer mill and cone collector.

On 10/24/2016 I visited the site and met with the Feed Department Head, Mr. Bill Wilson. Stephenson Marketing Association is still operating as a feed mill/grainery. Mr. Wilson stated the original equipment permitted in 1975 is still in operation.

The cone collector referred to in PTI #457-74 is a cyclone dust collector. This is inline following the hammer mill. The collector has been maintained and repaired over the years, patching holes as they have occurred. It is in the company's best interest to maintain the unit as any lost material (fugitive emissions) would be lost product and costly to the company. It appears to be in good operating condition.

No violations of the Air Pollution control Rules or PTI #457-74 were observed during this inspection.

NAME 

DATE 11/2/16

SUPERVISOR 