

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: On-site Inspection

P091459330

FACILITY: Steve's Autobody		SRN / ID: P0914
LOCATION: 57440 10 Mile Road, SOUTH LYON		DISTRICT: Warren
CITY: SOUTH LYON		COUNTY: OAKLAND
CONTACT: Steve Lloyd , Owner		ACTIVITY DATE: 07/30/2021
STAFF: Adam Bogнар	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Scheduled Inspection		
RESOLVED COMPLAINTS:		

On Friday July 30, 2021, Michigan Department of Environment, Great Lakes, and Energy, Air Quality Division (EGLE-AQD) staff, I, Adam Bogнар, conducted a scheduled inspection of Steve's Autobody located at 57440 10 Mile Road, South Lyon, MI 48178. The purpose of this inspection was to determine the facility's compliance status with the Federal Clean Air Act; Article II, Part 55, Air Pollution Control of Natural Resources and Environmental Protection Act, 1994 Public Act 451; and Michigan Department of Environment, Great Lakes, and Energy, Air Quality Division (EGLE-AQD) rules.

I arrived at the site around 12:30 pm. This facility is the source of an odor complaint received on April 8, 2020 (previously resolved). This complaint, and past complaints, are the primary reason that this facility was targeted for inspection in FY2021. There has not been a complaint against this facility in 2021. No painting was occurring during my inspection. I did not notice any odors outside the facility.

I met with Mr. Steve Lloyd, Owner. I identified myself and stated the purpose of the inspection. Mr. Lloyd gave me a tour of the facility. Steve's Autobody performs maintenance activities on automobiles. Mr. Lloyd is the only full-time employee. Mr. Lloyd has other employees that come help him out on a part time basis. There is one downdraft paint booth. I observed that the filters were in place and fit snugly such that there were no gaps in the filter. Paint usage records are kept. Mr. Lloyd provided me with these records. Reported paint usage is less than 1 gallon per month in all cases. The highest reported usage was in October 2020 at 82 fluid ounces (0.64 gallons). This booth appears to be exempt from Rule 201 requirements pursuant to Rule 287 (2)(c).

Mr. Lloyd said that his business has not been greatly affected by Covid-19 pandemic. After a brief period of decreased customer demand in early 2020 (beginning of pandemic), he is now seeing around the same customer demand as before the pandemic.

There is a paint mix area that appeared to be organized. All coatings had their lids on. The waste paint drum was equipped with a sealed cap during this inspection.

I left the facility at around 1 pm.

Compliance Determination

Steve's Autobody appears to be in compliance with the requirements of the federal Clean Air Act; Part 55, Air Pollution Control, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (Act 451); and Michigan Department of Environment, Great Lakes, and Energy-Air Quality Division (EGLE-AQD) Administrative Rules.

NAME Adam Bogнар

DATE 8/13/2021

SUPERVISOR K. Kelly