P1322

MANTLA

## DEPARTMENT OF ENVIRONMENTAL QUALITY AIR QUALITY DIVISION ACTIVITY REPORT: On-site Inspection

P132273461

RUSHING	SRN / ID: P1322	
), ROMULUS	DISTRICT: Detroit	
	COUNTY: WAYNE	
er Responsible Official	<b>ACTIVITY DATE:</b> 09/03/2024	
COMPLIANCE STATUS: Compliance	SOURCE CLASS: Minor	
SUBJECT: Concrete Crushing and fugitive dust management		
RESOLVED COMPLAINTS:		
	er Responsible Official  COMPLIANCE STATUS: Compliance	

## **Facility Background**

Tore Corp was permitted to install and operate a set of concrete crushing equipment at the 37500 Northline address on 11/1/22.

## **Inspection Narrative**

I arrived at the facility on September 3, 2024 to conduct compliance inspection of the crushing process. I met with Deanna Osborne and Richard Osborne-the owners and operators of the facility permited under General Permit# 138-22.

Deanna informed that this equipment had been disabled and was not in operation. The management contacted the Permit section in Lansing for addressing the permit status.

Staff awaits the notice from the Lansing office regarding the outcome of determinations on permitting requests put in by the Company.

## **Determination:**

The facility (P1322) was in compliance with the EGLE-AQD air quality control rules listed in the General permit# 138-22.

NAME DATE 10/124	SUPERVISOR
------------------	------------