

DEPARTMENT OF ENVIRONMENTAL QUALITY  
 AIR QUALITY DIVISION  
 ACTIVITY REPORT: Scheduled Inspection

U03161135438278

FACILITY: Ropes Courses Inc.		SRN / ID: U031611354
LOCATION: River Street, Allegan		DISTRICT: Kalamazoo
CITY: Allegan		COUNTY: ALLEGAN
CONTACT: Brad Ade ,		ACTIVITY DATE: 01/11/2017
STAFF: Dale Turton	COMPLIANCE STATUS: Compliance	SOURCE CLASS:
SUBJECT:		
RESOLVED COMPLAINTS:		

An inspection was conducted at the River Street location for this company. Since there are no offices at that location as of yet, I stopped off at the Lincoln Road headquarters and contacted Brad. Brad and I then proceeded down to the plant and completed the inspection.

This plant houses one large coating booth, located in the center of the building . This is capable of handling steel pieces used as support members for their structures. The filter bank is located at the back end and the stack goes up through the roof.

At this time the company is not using the booth. All of the painting is presently being done at the main plant on Lincoln Road. Nevertheless, the company is keeping acceptable records of the coating and reducer usage. The usage and emissions were zero for the year 2016. They are in compliance with the requirements of Rule 287c, since they are keeping records and the usage is less than 200 gallons per month.

This plant is now being used primarily for fabrication and welding. There were no visible emissions or odors detected from the outside of the building.

NAME Dale Turton

DATE Jan 12, 2017 SUPERVISOR MB 1/12/2017