



GRETCHEN WHITMER
GOVERNOR

STATE OF MICHIGAN
DEPARTMENT OF
ENVIRONMENT, GREAT LAKES, AND ENERGY
LANSING



LIESL EICHLER CLARK
DIRECTOR

November 25, 2019

UPS NEXT DAY DELIVERY

Mr. Charlie Martin
21st Century Salvage
Next Generation Environmental, Inc.
10750 Martz Road
Ypsilanti, Michigan 48197

Mr. Michael Samhat
Crown Enterprises, Inc.
MSC Land Company, LLC
12225 Stephens Road
Warren, Michigan 48089

SRN/ID: U821810662; Wayne County

Dear Mr. Martin and Mr. Samhat:

VIOLATION NOTICE

On November 6, 2019, the Department of Environment, Great Lakes, and Energy (EGLE), Air Quality Division (AQD) performed an asbestos inspection located at 1491 West Jefferson Avenue, Trenton, Wayne County, Michigan. The purpose of this inspection was to determine compliance with the requirements of Title 40 of the Code of Federal Regulations, Part 61, Subpart M (National Emission Standard for Asbestos), and Rule 942 of Part 55, Air Pollution Control of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended (Act 451).

According to our investigation, 21st Century Salvage, Next Generation Environmental, Inc., was the operator who conducted the demolition and abatement activities, and Crown Enterprises, Inc., MSC Land Company, LLC is the property owner of the address mentioned above. The National Emission Standard for Asbestos holds the *owner and operator* liable for all violations.

During the investigation staff observed the following:

The staff observed the demolition of one of the ovens at McLouth Steel. The ovens were being demolished as asbestos containing due to safety concerns if they were abated prior to demolition. During the demolition of the oven there was a large cloud of dust (visible emissions) that traveled North of the location and eventually off site. There was water being used prior and during demolition. Per the NESHAP, there can be no visible emissions if the structure is being demolished as asbestos containing.

Process Description	Section Violated	Comments
Visible emissions were observed during the demolition of stove which was demolished as asbestos containing.	§61.150(a)(1)(ii)	Visible emissions from handling operations.

Please initiate actions necessary to correct the cited violation and submit a written response to this violation notice by December 16, 2019, (which coincides with 21 calendar days from the date of this letter). The written response should include: the date(s) the violation occurred; an explanation of the causes and duration of the violation; whether the violation is ongoing; a summary of the actions that have been taken and are proposed to be taken to correct the violation, and the date(s) by which these actions will take place; and what steps are being taken to prevent a reoccurrence. The *signed* written response from the *owner and operator* to this violation notice, may be submitted by mail and directed to my attention at: EGLE, AQD, P.O. Box 30260, Lansing, Michigan 48909-7760. You must also include a copy to Mr. Jason Wolf, Enforcement Unit at: EGLE, AQD, P.O. Box 30260, Lansing, Michigan 48909-7760. The response may be scanned and emailed to brownj9@michigan.gov and wolfj2@michigan.gov.

If you believe the above observations or statements are inaccurate or do not constitute a violation of the applicable legal requirements cited, please provide appropriate factual information to explain your position.

Thank you for your attention to resolving the violation cited above and for the cooperation extended to me during our conversation. If you have any questions regarding the violation notice or the actions necessary to bring this facility into compliance, please contact me at 517-599-7825; brownj9@michigan.gov; or the post office box address provided in the paragraph above.

Sincerely,



Jeremiah Brown
Environmental Quality Analyst
Air Quality Division

cc: Ms. Mary Ann Dolehanty, EGLE
Dr. Eduardo Olaguer, EGLE
Mr. Christopher Ethridge, EGLE
Ms. Wilhemina McLemore, EGLE
Mr. Jason Wolf, EGLE
Ms. Karen Kajiya-Mills, EGLE
Ms. Tammy Bell, EGLE
Ms. Carrie Geyer, EGLE