

DEPARTMENT OF ENVIRONMENTAL QUALITY

AIR QUALITY DIVISION

FCE Summary Report

Facility : VIBRACOUSTIC USA, INC.	SRN : A6445
Location : 180 DAWSON ST	District : Bay City
	County : SANILAC
City : SANDUSKY State: MI Zip Code : 48471	Compliance Status : Compliance
Source Class : SM OPT OUT	Staff : Gina McCann
FCE Begin Date : 3/2/2017	FCE Completion Date : 2/17/2021
Comments : FCE	

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
01/28/2021	On-site Inspection	Compliance	Inspection of PTI 145-07C.
12/03/2020	Other Non ROP	Compliance	Air Stripper Monitoring Quarterly Report
07/16/2020	Other Non ROP	Compliance	Air Stripper Monitoring Quarterly Report. VOC, C&T DCE, and TCE emission rates are all well below lb/hr permit limits. Facility missed the second breakthrough check of the carbon canister in April, 2020. Special condition VI.3 of EUAIRSTRIPPER requires the canister be checked once every two weeks. Staff contacted Vibracoustics. Vibracoustic confirmed the second sampling was missed but reaffirmed the facility was in compliance both before and after. Using enforcement discretion, no violation notice was written.
04/13/2020	MAERS	Compliance	MAERS
03/30/2020	Other Non ROP	Compliance	Air Stripper Monitoring Quarterly Report. VOC, C&T DCE, and TCE emission rates are all well below lb/hr permit limits.
01/17/2020	Other Non ROP	Compliance	Air Stripper Monitoring Quarterly Report.

Activity Date	Activity Type	Compliance Status	Comments
09/18/2019	Other Non ROP	Compliance	Air stripper unit monitoring quarterly report. VOC, DCE and TCE emission rates are all well below lb/hr permit limits. There was a breakthrough on DCE on 1/8/19, but the pph was 0.0015, half of the permitted 0.003 pph. The next sampling on 1/22/19 was back to normal removal efficiencies.
09/18/2019	Other Non ROP	Compliance	Air stripper unit monitoring quarterly report.VOC, C&T DCE, and TCE emission rates are all well below lb/hr permit limits.
09/18/2019	Other Non ROP	Compliance	Air Stripper Monitoring Quarterly Report. VOC, C&T DCE, and TCE emission rates are all well below lb/hr permit limits.
09/17/2019	Other Non ROP	Compliance	Air stripper unit monitoring quarterly report. VOC, C&T, and TCE emission rates are all well below lb/hr permit limits.
02/19/2019	MAERS	Compliance	MAERS
08/21/2018	Other Non ROP	Compliance	Air stripper unit monitoring quarterly report- VOC, C&T, and TCE emission rates are all well below lb/hr permit limits.
06/27/2018	Other Non ROP	Compliance	Air stripper unit monitoring quarterly report. VOC, C&T, and TCE emission rates are all well below permit limits.
03/19/2018	Other Non ROP	Compliance	Air stripper unit monitoring quarterly report. There were a few formatting issues in this report (dates being for the wrong years, flow rate averages being different in the front report vs table 1.0) Contacted Debra Sopczynski HSE/Document Control Coordinator to address these issues in future reports.
01/03/2018	Other Non ROP	Compliance	Air stripper unit monitoring quarterly report- below lbs per hour thresholds for VOC, TCE and 1,1 DCE MK
11/13/2017	Other Non ROP	Compliance	Air stripper unit monitoring quarterly report- below lbs per hour thresholds for VOC, TCE and 1,1 DCE MK
06/12/2017	Other Non ROP	Compliance	Air stripper unit monitoring quarterly report
04/17/2017	Other Non ROP	Compliance	Air stripper unit monitoring quarterly report
04/11/2017	MAERS	Compliance	MAERS


Name:



Date:

2/27/2021

Supervisor:


Page 2 of 2