

DEPARTMENT OF ENVIRONMENTAL QUALITY

AIR QUALITY DIVISION

FCE Summary Report

Facility : DTE Electric Company - Wilmot Peaking Facility	SRN : B2804
Location : 5977 EAST BEVENS ROAD	District : Bay City
	County : TUSCOLA
City : KINGSTON TWP State: MI Zip Code : 48741	Compliance Status : Compliance
Source Class : MAJOR	Staff : Emily Crimmins
FCE Begin Date : 11/21/2023	FCE Completion Date : 11/21/2024
Comments : FCE for FY25 inspection	

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
11/21/2024	On-site Inspection	Compliance	On-site inspection of MI-ROP-B2804-2023.
09/25/2024	ROP Semi 1 Cert	Compliance	Semiannual report received by AQD staff on 9/11/24. No deviations reported for the reporting period of 01/01/24 to 6/30/24.
09/25/2024	MACT (Part 63)	Compliance	Subpart ZZZZ Semiannual compliance report. No deviations reported for the reporting period of 01/01/24 to 6/30/24. No Carbon Monoxide CMS reporting to report for the period of 01/01/24 to 6/30/24.
04/02/2024	Annual Emissions Report (or MAERS)	Compliance	The ROP Certification form was submitted and received for the electronic submittal of the 2023 MiEnviro annual emissions report. The report was properly certified and received on time. The 2023 annual emissions report will be reviewed at a later date (D. King 4/2/24)
04/02/2024	ROP Annual Cert	Compliance	The ROP annual compliance report was submitted and received by the AQD. The report was properly certified and received on time. During this reporting time period no deviations were reported. (D. King 4/2/24)

Activity Date	Activity Type	Compliance Status	Comments
04/02/2024	ROP SEMI 2 CERT	Compliance	The ROP semi annual compliance report was submitted and received by the AQD. The report was properly certified and received on time. During this reporting time period no deviations were reported. (D. King 4/2/24)
04/02/2024	MACT (Part 63)	Compliance	The 40 CFR Part 63 Subpart ZZZZ semi annual compliance report was submitted and received by the AQD. The report was properly certified and received on time. During this reporting time period no deviations were reported. (D. King 4/2/24)
01/12/2024	Stack Test	Compliance	Per MI-ROP-B2804-2018 and NESHAP Subpart ZZZZ, emissions testing was completed to verify carbon monoxide (CO) destruction efficiency for Units 11-1 through 11-5. Test results showed for each engine either a 70% or more destruction efficiency or an outlet emission rate of less than 23 ppm. Process data appears consistent with what was observed during the stack testing. Some parameters recorded were not initially provided in the report and were later provided via email. This appears acceptable. (AShaffer, 01/12/24)

Emily Steimmins

Name: _____

Date: 12/04/2024

Supervisor: _____

D. King