

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION

FCE Summary Report

Facility : BUCKEYE PIPE LINE HOLDINGS, L.P.- TAYLOR TERMINAL	SRN : B9036
Location : 24801 ECORSE RD	District : Detroit
	County : WAYNE
City : TAYLOR State: MI Zip Code : 48180	Compliance Status : Compliance
Source Class : SM OPT OUT	Staff : C. Nazaret Sandoval
FCE Begin Date : 04/30/2020	FCE Completion Date : 4/30/2021
Comments : FCE for FY2021	

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
04/30/2021	MAERS	Compliance	MAERS report for 2020 emissions was timely submitted on 3/10/2021. AQD audited the report and passed it on 4/30/2021. For audit details refer to the Activity Report No. CA_B903657819
04/30/2021	Other	Compliance	MAERS Audit Report - Comments to the 2020 emission report submitted on 3/10/2021. For audit details please see CA_B903657819
03/12/2021	On-site Inspection	Compliance	FY 2021 Targeted Inspection - For details about this inspection refer to report CA_B903657818

Activity Date	Activity Type	Compliance Status	Comments
05/08/2020	MAERS	Compliance	<p>MAERS report for 2019 emissions was electronically submitted on 3/12/2020. AQD audited the report and completed/passed it on 5/8/2020. Please refer to the audit comments below.</p> <p>The terminal uses the TANK model to estimate working/breathing losses from storage tanks. In 2019 the total VOC emissions (18,323 pounds) were slightly higher than the emissions reported for year 2018 (17,581 pounds) which correlates with increase in fuel loading. The highest VOC contribution comes from truck rack loading operations representing 59.5 % of the total, 35% from tanks standing/working losses, and the remaining 5.5 % are from fugitives emissions and (1) tank cleaning. There were no roof landings year. The changes in VOC emissions for the individual EUs correlate with throughputs and historical data. The facility seems to be operating within the permit material limits.</p>

Name: Nazaret Sandoval

Date: 5/11/2021

Supervisor: JK