

**DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
ACTIVITY REPORT: Scheduled Inspection**

N081043828

FACILITY: ROBINSON INDUSTRIES INC		SRN / ID: N0810
LOCATION: 4451 N M18, COLEMAN		DISTRICT: Saginaw Bay
CITY: COLEMAN		COUNTY: MIDLAND
CONTACT:		ACTIVITY DATE: 03/16/2018
STAFF: Benjamin Witkopp	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Facility inspection		
RESOLVED COMPLAINTS:		

Ben Witkopp and Matt Karl of the Michigan Department of Environmental Quality - Air Quality Division (MDEQ-AQD) went to Robinson Industries second facility located at 4451 N M 18. It's primary location is located on Curtice Rd jus a few miles north and we had gone there first and met with Mr. John Bradac. I had previously toured the operations in 2001, and the facility subsequently voided the permit (107-90) it had as the operations were deemed exempt from permitting.

Whereas the Curtice Rd facility does extrusion and thermoforming, the M 18 site does plastic injection molding. The facility's primary product is plastic pallets.

The facility still has a wash sink (cold cleaner). It has the proper operating information I shared with John in 2001 posted by the unit.

The facility is considered in compliance and the operations witnessed at the time were indeed still exempt from permitting.

NAME B. Witkopp

DATE 7-19-18

SUPERVISOR C. Hove