

Benteler Automotive  
3721 Hagen Dr., S.E.  
Grand Rapids, MI 49548  
616-245-4607

Automotive



**DATE: January 31, 2018**

**TO: DEQ, Air Quality Division**

**FROM: Alycia Provenzo, SHE Manager, SHE Department, Benteler Automotive**

---

Dear DEQ Representative,

I am writing in response to DEQ letter notification received January 12, 2018 SRN: N2525, Kent County ("Violation Notice"). A copy of the Violation Notice is attached. The violations were identified on January 8, 2018 during an inspection performed by April Lazzaro. I have addressed the violations cited in Violation Notice. Enclosed is evidence that each of the violations has been corrected.

We have repaired the seam of TMI unit #7 (1/26/2018). All filter house units are currently functioning and are in operation. An additional PM was created to inspect the units on a monthly basis to address covers, drop chutes, drum lids, seams, particulates and other discrepancies. These new inspection procedures will prevent recurrence of violations.

Attached is a record of our facility wide rolling HAPS and CAPs for 2016 and 2017. A copy of our formal PM generated from our SAP system is also attached.

As requested, I have also prepared a facility-wide potential to emit demonstration, which is attached.

Please contact the undersigned if you have any questions.

---

Thank you,



Alycia M. Provenzo  
Safety Health Environmental Manager

**Automotive Division**

3721 Hagen Dr. SE | Grand Rapids | Michigan 49548 | USA  
Tel: +1 616-248-5528 | Mobile +1 616-340-4067  
[alycia.provenzo@benteler.com](mailto:alycia.provenzo@benteler.com) | [www.benteler.com](http://www.benteler.com)