## **STAFF REPORT**

## Michigan Department of Environment, Great Lakes, and Energy

Liquid Ind.Waste/Pt.121  Hazardous Waste/Pt.111  Scrap tire/Pt.169  Other	Complaint Inspection Compliance Inspection Construction/Closure Inspection Permitting Inspection PEAS Investigation	Corrective Action Sampling Inspection Telephone Call Meeting Notes Other
Facility/Site Name Arbor Hills Landfill		Date/Time 10-20-2023 8:00am-8:35am
Address 10699 W. Six Mile Road Participants/Contacts		Facility/Site Number WDS 475946 Staff
Anthony Testa		Gary Schwerin
REFERRED TO:		
REMARKS (weather, unusual conditions, etc.):		
REMARKS (weather, unusual conditions, etc.): After receiving numerous odor complaints, I completed an odor inspection		
near Arbor Hills Landfill. Temperature was 54°, misty, and SW wind at 3 mph. Time rounded to nearest 5 min.		
I completed inspections and made the noted observations at the following locations:		
Strong LFG odor (3) at Napier Road approximately 150 feet south of the landfill entrance from 8:00 am to 8:10 am		
50333 Briar Ridge Lane – No odor at 8:15am		
50937 Briar Ridge Lane – Medium intensity LFG odor (2.5) at 8:20am		
17369 Briar Ridge Lane - Medium intensity LFG odor (2.5) at 8:20am		
17475 Briar Ridge Lane - Light LFG odor (2) at 8:25am		
17369 Briar Ridge Lane - Medium intensity LFG odor (3) at 8:25am		
50937 Briar Ridge Lane – Medium intensity LFG odor (3) at 8:25am		
Strong LFG odor (3) at Napier Road from the landfill drive entrance to approximately 200 feet south at 8:35 am		

DISTRIBUTION/CC:	
Signature	
	Pageof