

DEPARTMENT OF ENVIRONMENTAL QUALITY

AIR QUALITY DIVISION

N6013 - FCE - 2015 08 06

FCE Summary Report

Facility : CONTINENTAL ALUMINUM	SRN : N6013
Location : 29201 MILFORD RD	District : Southeast Michigan
	County : OAKLAND
City : NEW HUDSON State: MI Zip Code : 48165	Compliance Status : Non Compliance
Source Class : SM OPT OUT	Staff : Iranna Konanahalli
FCE Begin Date : 7/14/2014	FCE Completion Date : 8/6/2015
Comments : Not in compliance. AQD issued violation notices: February 5, 2013 (for failure to comply with NESHAP / MACT RRR / MACT 3R, 40 CFR, Part 63, Subpart RRR [Secondary Aluminum Production NESHAP]), September 10, 2014 (for failure to operate RO lime feeder), Ju	

List of Partial Compliance Evaluations :

Activity Date	Activity Type	Compliance Status	Comments
07/31/2015	Scheduled Inspection	Non Compliance	FY 2015 scheduled annual inspection of Continental Aluminum ("Continental")
06/23/2015	Complaint Investigation	Compliance	FY 2015 complaint investigation - Continental Aluminum (N6013)
04/27/2015	Other	Compliance	September 24-26, 2013 (RO [Baghouse under two conditions: Condition1 - max. flux and Condition2 - max. temperature & minimum required lime] and RV1 (sidewell Baghouse)), and June 12-13, 2014 (natural gas fired RV1 combustion / hearth stack - uncontrolled, i.e., no baghouse) Stack Tests
09/23/2014	Complaint Investigation	Non Compliance	FY 2014 Complaint Investigation
09/03/2014	Complaint Investigation	Non Compliance	FY 2014 complaint investigations - Continental Aluminum

Name:

*Iranna Konanahalli*

Date:

*08/06/2015*

Supervisor:

*CJE*