

**DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
ACTIVITY REPORT: Self Initiated Inspection**

N618039457

FACILITY: WARD LAKE ENERGY, CHARLTON 21 CPF		SRN / ID: N6180
LOCATION: T30N R1W SEC 21, GAYLORD		DISTRICT: Gaylord
CITY: GAYLORD		COUNTY: OTSEGO
CONTACT:		ACTIVITY DATE: 04/20/2017
STAFF: Gloria Torello	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Site visit to assess request to void permit 3-97B.		
RESOLVED COMPLAINTS:		

The purpose of the site visit was to assess the permittee's request to void permit 3-97B.

There is an empty pad where the engine was located. The building housing the engine was removed. Remaining are two large tanks in a lined retaining area, a glycol dehydrator located out of doors, an iron sponge, and other misc. equipment.

With the engine removed, there is not an objection to voiding permit 3-97B.

NAME *Gloria Torello*      DATE 4-21-17      SUPERVISOR SN