

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Scheduled Inspection

N659035437

FACILITY: R H HUHTALA AGGREGATES INC #75-01		SRN / ID: N6590
LOCATION: T 49N R 34W SE 1/4 SE 1/4 Sec 12, LANSE		DISTRICT: Upper Peninsula
CITY: LANSE		COUNTY: BARAGA
CONTACT: ROLAND H HUHTALA , OWNER		ACTIVITY DATE: 07/08/2016
STAFF: Joel Asher	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: Portable gravel crusher		
RESOLVED COMPLAINTS:		

On 7/8/2016 I conducted an unannounced inspection of this facility. My primary contact was the owner, Mr. Roland Huhtala.

This facility is a portable aggregate crushing operation that is permitted under PTI #75-01. At the time of this inspection the facility was operating at the Williams Redi-Mix Paint River Pit #1, north of Crystal Falls. They started operations at this location on 7/7/2016. They plan to remain at this location until 7/15/2016.

The following equipment was observed in operation:

Jaw crusher 9901

Feeder 8002

Screen 0101

Cone crusher 9801

Conveyor 1201

Conveyor 0003

Conveyor 9701


Radial Stacker 0201

All equipment is presently covered under PTI #75-01. All required equipment has had the required Visible Emission readings conducted.

No visible emissions were observed from the operations. Water is applied and a large water tank was observed on site. Water is obtained from the pit on site.

I met with Mr. Brad Huhtala and observed the facility's permit to be kept on site. Records of operations and material produced were also observed.

The facility appears to be operating in compliance with their air use permit. No violations of PTI #75-01 or the Air Pollution Control Rules were observed during this inspection.

NAME 

DATE 7/11/16

SUPERVISOR 