

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: On-site Inspection

N679362828

FACILITY: RIVERSIDE ENERGY MICHIGAN, LLC - Chester 16		SRN / ID: N6793
LOCATION: SW NE SW Sec 16, GAYLORD		DISTRICT: Gaylord
CITY: GAYLORD		COUNTY: OTSEGO
CONTACT:		ACTIVITY DATE: 05/09/2022
STAFF: David Bowman	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT:		
RESOLVED COMPLAINTS:		

On 9 May 2022 I, David Bowman EGLE-AQD, inspected Chester 16 West CPF. Source is a true minor. The site is found by accessing the drive that leads to the quarry just east of Dreffs Rd, just east of 5335 McCoy Rd. From McCoy road there is no sign indicating presence of the source. Signage at the site lists location of Chester 16 West CPF as T30N-R2W Sec16 SE1/4 NE1/4 SW1/4. Site was cleaned and maintained. Skid GCS 795 was located inside the shed, this is the same as noted in last inspection. Records for monthly inspections were present and being filled out. Digital display showed RPM at 974, and the data plate listed the engine as SN 4K00337. manual gauges showed normal operating parameters for an engine. The engine had no control and exhaust exited horizontally to a muffler then angled vertical to approximately 12' AGL. The glycol dehydrator was present and operational. There was no discernable odors and no visible emissions other than the heat shimmer from the stack. There was no obvious changes to the site since the last inspection.

NAME _____

DATE _____

SUPERVISOR _____