

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: On-site Inspection

N708461138

FACILITY: Riverside Energy Michigan, LLC - Bagley 16		SRN / ID: N7084
LOCATION: SECTION 16, BAGLEY TWP		DISTRICT: Gaylord
CITY: BAGLEY TWP		COUNTY: OTSEGO
CONTACT:		ACTIVITY DATE: 12/14/2021
STAFF: David Bowman	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: onsite inspection to verify exempt status- site has been removed		
RESOLVED COMPLAINTS:		

On 12.14.21 AQD Inspector David Bowman inspected Riverside Bagley 16 N7084 – Exempt site. Site is located on McCoy rd approximately 0.5 miles west of the McCoy and Dickerson rd intersection. Upon arrival to the site I found the equipment had been removed from the site and the drive closed with a no trespassing sign present. There are electric boxes present but not connected to anything.



David Bowman,
Environmental Engineer
NAME _____

Digitally signed by David
Bowman, Environmental Engineer
Date: 2021.12.17 07:26:06 -05'00'

DATE _____

Shane Nixon, Cadillac/
Gaylord District Supervisor
SUPERVISOR _____

Digitally signed by Shane Nixon,
Cadillac/Gaylord District Supervisor
Date: 2021.12.17 07:26:36 -05'00'

