

**DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: On-site Inspection**

N718974798

FACILITY: VCP Michigan - Vienna 18		SRN / ID: N7189
LOCATION: NW NW SE SEC 18, VIENNA TWP		DISTRICT: Cadillac
CITY: VIENNA TWP		COUNTY: MONTMORENCY
CONTACT:		ACTIVITY DATE: 12/02/2024
STAFF: Tammie Puite	COMPLIANCE STATUS: Compliance	SOURCE CLASS: MINOR
SUBJECT: 2025 Minor FCE Inspection		
RESOLVED COMPLAINTS:		

This is a source that has no active permits and is operating under exemptions. I sent a records request to VCP on November 25, 2024. Jeremy Lewandowski of ECT responded that the equipment has been removed from this location. So I did a site visit to determine that status of this source.

Once onsite, there is no longer any buildings, nor any equipment. Only a pump jack and a few pipes sticking out of the ground where the building was. Google Earth Imagery from 2016 shows that there was a building and 1 AST tank onsite.

I will close this source out, and remove it off of AQD lists.



Image 1(N7189) : Only Pipes left at the location.



Image 2(Pipes) : Only pipes left at location.



Image 3(Pump Jack) : Campbell C3-18

NAME 

DATE 12-4-24

SUPERVISOR 