

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Self Initiated Inspection

N723937252

FACILITY: Speedway		SRN / ID: N7239
LOCATION: G3247 South Linden Road, FLINT		DISTRICT: Lansing
CITY: FLINT		COUNTY: GENESEE
CONTACT: Ryan Sabol , Environmental		ACTIVITY DATE: 10/07/2016
STAFF: Nathaniel Hude	COMPLIANCE STATUS:	SOURCE CLASS: MINOR
SUBJECT: Self Initiated inspection based on county file review and purging. Targeted due to having an older permit that generally uses temporary equipment.		
RESOLVED COMPLAINTS:		

Inspection Report

N7239- Speedway (former Total Station #2575)
G3247 S Linden Road
Flint, MI 48507

Inspection Date:

10/7/16

Facility Contacts:

Ryan Sabol, Speedway LLC, 937-863-7667, rtsabol@speedway.com
Jim Innes, MDEQ RRD, 517-284-5115, innesj@michigan.gov

MDEQ AQD Personnel:

Nathan Hude – 517-284-6779, huden@michigan.gov

Facility Description:

This site was a gas station operated as Total Station 2575 until being acquired by Speedway on an unknown date. The site is active with a device located on the east side of the lot, though the building has been demolished. The location is on the SE corner of Miller and Linden Rd.

The DEQ Storage Tank Information Database websites provide the following information:

Facility ID: 00009414

LUST Site Name: Total # 2575

Leak ID: C-0805-91, Discovery Date: 4/26/1991, Substance: no info, Release Status: Open

Leak ID: C-2643-91, Discovery Date: 12/11/1991, Substance: unknown, Release Status: Open

Leak ID: C-1336-01, Discovery Date: 10/24/2001, Substance: unknown, Release Status: Open

Owner Information: Speedway LLC, PO Box 1500, Springfield, OH 45501, Phone#: (937) 864-3000

http://www.deq.state.mi.us/sid-web/Tank_Detail.aspx?mod=lust&Site_ID=00009414

Permit Cards identifies the Company Contact as:

Mr. C. Shay Wideman, TPI Petroleum Incorporated, PO Box 696000, San Antonio, TX 78269-6000

Applicable Regulations:

PTI 69-03

Previous Inspections:

none

Previous Violations:

none

Recent Complaints (within 2 years):

none

Number of Violations Found During this Inspection:

none

Inspection Key Concerns:

none

MAERS Reporting

none

MAERS Emission Unit List

none

Inspection Summary

I stopped to inspect this site on 10/7/16. The site is an inactive gas station; there are no standing buildings on the site. A remediation device in an enclosed trailer is on site located on the east side of the lot and is enclosed by a wooden fence. I was able to look through the fence and saw that the breaker switch was in the off position; no noise was coming from the trailer.

On 10/20/16, I emailed Ryan requesting documentation of compliance in accordance with the permit. We discussed this request again while on the phone on 10/24/16. I again emailed Ryan on 11/2 requesting a response by 11/4.

Jason Siemen responded on 11/2 stating that the device had not been operated since 2009 and is scheduled to be removed later this quarter. I asked Jason to contact me at that point and we would then void the permit.

Based on the lack of operations, records were not requested. It appears this site is in compliance with the appropriate permit and rules.




Image 1(Device) : Device

NAME A. [Signature]

DATE 11/21/16

SUPERVISOR B. M. [Signature]

