

DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
**ACTIVITY REPORT: On-site Inspection**

N781362855

<b>FACILITY:</b> RIVERSIDE - OTSEGO LAKE 12 (PART OF CHESTER 7)		<b>SRN / ID:</b> N7813
<b>LOCATION:</b> SW 1/4 SEC 31 T30N R2W, CHESTER TWP		<b>DISTRICT:</b> Gaylord
<b>CITY:</b> CHESTER TWP		<b>COUNTY:</b> OTSEGO
<b>CONTACT:</b>		<b>ACTIVITY DATE:</b> 05/12/2022
<b>STAFF:</b> David Bowman	<b>COMPLIANCE STATUS:</b> Compliance	<b>SOURCE CLASS:</b> MINOR
<b>SUBJECT:</b> unscheduled inspection.		
<b>RESOLVED COMPLAINTS:</b>		

I conducted an unscheduled inspection of the site. Directions to it are Old 27 South from Gaylord to Charles Brink Rd, turning North on Club House Rd, then East on Ramona Trail. Take Ramona Trail until it becomes a seasonal rd. Approximately 500 feet east of the T intersection with Chester Trail the trail to the south leads to a gate that is seen from Ramona Trail. It was open today, but has a sign that states it is to be kept closed at all times.

The pipeline coming into the facility has been disconnected from the site. There are two 500 bbl tanks in secondary storage and one lone approx 300 bbl tank in the field. In the shed there is a glycol dehy that is not operating and NO compressor engine. The site has not operated since 2014 per previous reports. Previous reports state that the source did not want to void the PTI.

NAME \_\_\_\_\_

DATE \_\_\_\_\_

SUPERVISOR \_\_\_\_\_