

**DEPARTMENT OF ENVIRONMENTAL QUALITY  
AIR QUALITY DIVISION  
ACTIVITY REPORT: Self Initiated Inspection**


N832437582

FACILITY: SPEEDWAY SUPERAMERICA LLC (SSA 8830)		SRN / ID: N8324
LOCATION: 6980 ROCHESTER RD (STORE 8830), ROCHESTER HLS		DISTRICT: Southeast Michigan
CITY: ROCHESTER HLS		COUNTY: OAKLAND
CONTACT:		ACTIVITY DATE: 11/04/2016
STAFF: Kerry Kelly	COMPLIANCE STATUS: Compliance	SOURCE CLASS: Minor
SUBJECT:		
RESOLVED COMPLAINTS:		

On November 4, 2016, Sam Liveson, Jill Zimmerman, and I (Kerry Kelly) conducted a self-initiated inspection at Speedway LLC located at 6980 North Rochester Road in Rochester, Michigan. The purpose of the inspection was to determine if the air sparging (AS) and soil vapor extraction (SVE) equipment, permitted in General Permit 211-09, had been removed from the site and whether emissions were being generated from the AS/SVE processes.

General Permit number 211-09 was issued to Speedway for soil or groundwater remediation equipment on September 10, 2009. According to a letter AQD received from Speedway on September 27, 2016, the AS/SVE equipment was removed on August 27, 2013. In the same letter Speedway requested permit number 211-09 be voided.

Sam, Jill and I arrived at Speedway at approximately 11:30 AM and met with Mr. Mike Cox, Geologist, Practical Environmental Consultants, Inc. Mr. Cox showed us a concrete pad in the southwest corner of the property where the above-ground DPE equipment had been located. Mr. Cox also showed us where the trunk line and wells were located below ground. I did not observe any emission points from the where the AS/SVE equipment was located. After returning to the office I researched Google Maps street view images August 2013 (Photo dated August 2013) and July 2015 (Photo dated July 2015). I observed a trailer in the August 2013 Google street view. The trailer was located in the same area as the concrete pad I inspected. The trailer was absent in the July 2015 Google image. Following my inspection and research I concluded the above ground AS/SVE equipment had been removed from 6980 North Rochester Road, Rochester, Michigan. I will recommend, based on my research, inspection, and per the request of Speedway, AQD permit section void General Permit 211-09.



**Image 1(August 2013)** : Google street view from August 2013 of trailer outside Speedway




Image 2(July 2015) : Google street view taken in July 2015 of concrete slab inspected

NAME K. Kelley

DATE 11/14/16

SUPERVISOR SK