

DEPARTMENT OF ENVIRONMENTAL QUALITY
AIR QUALITY DIVISION
ACTIVITY REPORT: Self Initiated Inspection

U0109020430324

FACILITY: Great Northern Lumber		SRN / ID: U01090204
LOCATION: 507 State Road, Lincoln		DISTRICT: Gaylord
CITY: Lincoln		COUNTY: ALCONA
CONTACT: Joel Blohm , Operations Manager		ACTIVITY DATE: 07/16/2015
STAFF: Gloria Torello	COMPLIANCE STATUS: Compliance	SOURCE CLASS:
SUBJECT: Site visit.		
RESOLVED COMPLAINTS:		

While in the county, Torello stopped into the sawmill and met with Mr. Joel Blohm, operations manager, 989-736-6192. The facility was operating. On the north side of the building saw dust was exiting the building via a conveyor and dropping to the ground. There was no stock pile. There was a breeze. There was dust blowing in the wind. The end of the conveyor had a pant leg approximately 3 feet long. There were gaps in the pant leg.

Per discussion with Mr. Blohm, he will work to: maintain a stockpile to minimized the drop distance, lengthen the pant legs, fill in the gaps on the pant legs, and potentially build a partial wall off the edge of the building.

The pant leg was recently installed and bolted together as an ongoing effort to minimize dust.

NAME Gloria Torello DATE 7-23-15 SUPERVISOR [Signature]