	Received DEQ/AQD
	AUG 2 3 2017
MACES_	MAERS:
FILE:	The second secon

To whom this may concern:

Here is all the paperwork that we obtained before tearing down the IGA Store in rapid river. We had the delta county landfill come out and inspect the property for hazardous materials . He told us to remove the wall thermostat (which we still have), all florescent light fixtures and bulbs (bulbs went to TKL repair to be used in their shop and the ballasts went to Coplans, all the paints and cleaners we also removed). We were never informed that we needed to get ahold of anyone else since the building did not contain asbestos. It was brought to our attention after the building was down that we needed to have it inspected by the DEQ. Max Constantino brought material to his near by residence to sort wire, metal and debris for the landfill as the lot the IGA was built on is smaller than the building itself. With the close proximity to US2 and the attention It brought from the public we felt that removing it and taking it somewhere else was a safer bet.

The violation occurred on July 30th 2017. It was unknow by both parties that any laws were being broken. The demolition took approximately 9 hours to complete. Included is the manifest from the wood island landfill, to correct the violation the day after meeting with Joseph. To prevent any reoccurrence we will not be rehabilitating anymore blight properties as the risk outweighs the reward.

Enclosed are the following documents: inspection from dswma, receipt from Coplan's disposing of some metal and ballasts, and the wood island landfill manifest.

COPLAN IRON & METAL 1610 7th Avenue North Escanaba, MI 49829 (906) 786-2462 Buyer X Date Material: 07 31 17 15:13 16380 lb 10800 lb 07 31 17 As the seller, I am the owner of the metal or I am authorized to sell the metal. I haven't been convicted of metal theft in the past. License Plate No.

WEIGHED ON DIGITAL INDICATOR & PRINTER

Trailer No.

Tractor No.

3100-4 Coplan (6/14)

Weighed By

127

DELTA SOLID WASTE MANAGEMENT AUTHORITY

P.O. Box 198 ESCANABA, MI 49829 Phone 906-786-9056 Fax 906-786-0825

don@dswma.org www.dswma.org

July 24, 2017

Pro Towing and Sales 7836 US 2 Rapid River, MI 49878 906-474-2220

Breanne:

I have done the inspection of the old Rob's Grocery in Rapid River on US 2 and the entire building can come into the landfill.

Please remove the thermostat on the wall at the checkout counter and all florescent light fixtures and bulbs. Also please remove the paints and cleaners in the building and any other liquids you find. Please recycle as much of the metal items like freezers and coolers as possible.

Included is your receipt for the inspection.

If you have any questions or need any help, please give me a call.

Sincerely:

Don Pyle Manager

cc dswma file

WASTE SHIPMENT RI (See Reverse for Instructions)	CORD/ASBES	TOS IVI	ANIFEST			For Disp	osal Site Use Only		
1-A.Special Waste Profile Number	1-A.Special Waste Profile Number NESHAP Notified WSR Number						Elevation		
	YES	7381			NorthEast				
1-B. Generator Name, Contact Name, RYAN CINDBERD	and Complete Mailing Addre	ess (includin	g Zip Code)		1-C. G	enerator's	Phone Number		
1-D. Work Site Address 7929 05-2 Papid Piusa Mt 4987 2. Operator's Name and Complete Mailing Address					1-E. 24 Hour Emergency Response Telephone Number				
2. Operator's Name and Complete Mai	ling Address		1900	11.	Operat	or's Phone	Number		
3. Waste Disposal Site (WDS) Name and Complete Mailing Address WOOD FSIAND LAND, N					WDS Phone Number				
4. Name and Address of Responsible Agency State of Wisconsin; Department of Natural Resources State of Michigan; Region 1 I						906-387-2646			
State of Wisconsin; Departmen 1125 Military Avenue, Green B			State of Michigan; 1990 US Highway						
5. Description of Materials				116.5 1 - 4 - 5 - 5 5 - 416.3	6. Cont No.	ainers Type	7. Total Quantity yd3		
friable asbestos		9, NA2212, III, RQ		200	•				
NN KNON		0							
non-friable asbestos		Cat I	_ Cat II	1	7,120				
8. Special Handling Instructions and A	ddilional Information PRIOR TO DISPOSAL, MU	ST BE BURI	ED		0,180	1	57.900		
GENERATOR/OPERATOR'S CERT ping name and are classified, packed, and government regulations. I hereby	marked, and labeled, and a	re in all resp	ects in proper condition	for transport by	y highway	according			
Printed/Typed Name and Title		Signature		Λ	Λ		Date		
10. Transporter 1 Company Name CONSTAINT: NO TRU Complete Mailing Address 8766 32 Nd RO RAPID RIVER C198 Telephone Number (including area cor 906 - 241 - 4) (18)		Printed Name and Ti	Ille		>			
11. Transporter 2 Company Name			Driver Signature		-				
Complete Mailing Address	, ·								
Telephone Number (including area code)			Printed Name and Ti	tle		***************************************			
			Date						
12. Discrepancy Indication Space									
	erator is issued by signature in the f asbestos materials covered								
Printed/Pyped Name and Title	Minister	Signature	ROY EDV	ook			Date d/2/1		

GOLD - Generator

PINK - Transporter

WHITE - Disposal Site

CANARY - Generator

Wood Island Landfill M-28-E-10081 P.O. Box 165 Wetmore, MI 49895 906-387-2646

892499

CUSTOME	R'S ORDER	NO.		DATE	12	10	7
NAME C	ONST	Ativ.	5 TK	110	<i>O</i> 1_	t	
ADDRESS			V =				
CITY, STATE	E, ZIP					-	
SOLD BY	CASH	C.O.D.	I CHARGE	ON, ACCT.	IMDSE. F	RETD PA	ID OUT
							114
QUAN.		DESCI	RIPTION		PRICE	AMO	UNT
1		TAG	60		9	21	20
2		528	160		_/.	206	00
3		6	7900	0	5		
4		70	780)	/	1	11
5	-	70	5780		1	1	
6		مسر	3/0)	>	70	Do
7		>0	1600			~U,	00
8 -						-	
9						500	100
10							
11							
12							
13							
14							
RECEIVED E	34				TAX	11.16719	
					TOTAL		
-24705W 46901		KEEP THI	S SLIP FO	R REFERE	VCE	to de anne	01-11