



GRETCHEN WHITMER  
GOVERNOR

STATE OF MICHIGAN  
DEPARTMENT OF  
ENVIRONMENT, GREAT LAKES, AND ENERGY  
DETROIT DISTRICT OFFICE



LIESL EICHLER CLARK  
DIRECTOR

June 28, 2019

Mr. Shane Dusseau  
3661 Rodesiler Hwy.  
Deerfield, MI 49238

Mr. Randy Crots  
Lasershot Inc.  
1661 Bucholtz Hwy.  
Deerfield, Michigan 49238

SRN: U461906434, Lenawee County

Dear Mr. Dusseau and Mr. Crots:

**VIOLATION NOTICE**

On June 17, 2019, the Department of Environment, Great Lakes, and Energy (EGLE), Air Quality Division (AQD), conducted an inspection of commercial building located at 118, 122 and 126 Carey St., Deerfield. The purpose of this inspection was to determine the owner's and operator's compliance with the requirements of Title 40 of the Code of Federal Regulations (CFR), Part 61, National Emission Standards for Hazardous Air Pollutants (NESHAP), Subpart M and Rule 942 of the administrative rules promulgated under Part 55, Air Pollution Control of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended.

According to our investigation, Mr. Shane Dusseau owns the building and Lasershot Inc. performed the demolition activities at the building. The NESHAP for Asbestos holds both the owner and operator equally liable for violations.

During the inspection, staff observed that demolition activities had begun without a thorough inspection for asbestos prior to demolition activities. A 10-day notice of intent to demolish had not been provided to the Air Quality Division.

Process Description	Section Violated	Comments
Demolition of an asbestos NESHAP subject commercial building.	40 CFR 61.145(a)(1)	Failure to thoroughly inspect for asbestos prior to demolition activities.
	40 CFR 61.145(b)(1)	Failure to provide 10-day notice of intent to demolish.
	40 CFR 61.145(c)(8)	Failure to have a supervisor trained in the asbestos NESHAP on site during demolition activities.

Mr. Shane Dusseau and Mr. Randy Crots

Page 2

June 28, 2019


Please initiate actions necessary to correct the cited violations and submit a signed written response to this Violation Notice by July 19, 2019 (which coincides with 21 calendar days from the date of this letter). The response should include: the dates the violations occurred; an explanation of the causes and duration of the violations; whether the violations are ongoing; a summary of the actions that have been taken and are proposed to be taken to correct the violations and the dates by which these actions will take place; and what steps are being taken to prevent a reoccurrence.

Please submit the written response to Tammy Bell at EGLE, AQD 3058 West Grand Boulevard, Suite 2-300, Detroit, Michigan 48202 or bellt4@michigan.gov and submit a copy to Mr. Jason Wolf, Enforcement Unit at EGLE, AQD, P.O. Box 30260, Lansing, Michigan 48909-7760 or wolfj2@michigan.gov.

If Mr. Shane Dusseau or Lasershot Inc. believes the above observations or statements are inaccurate or do not constitute violations of the applicable legal requirements cited, please provide factual information to explain your position.

Thank you for your attention to resolving the violations cited above and for the cooperation that was extended to me during my inspection of 118, 122 and 126 Carey St. Deerfield. If you have any questions regarding the violations or the actions necessary to bring this facility into compliance, please contact me at the number listed below.

Sincerely,



Tammy Bell  
Senior Environmental Quality Analyst  
Air Quality Division  
313-330-0105

Enclosure: Sample results and Fact Sheet

cc: Ms. Mary Ann Dolehanty, EGLE  
Dr. Eduardo Olaguer, EGLE  
Ms. Jenine Camilleri, EGLE  
Mr. Christopher Ethridge, EGLE  
Ms. Karen Kajiya-Mills, EGLE  
Mr. Jason Wolf, EGLE  
Mr. Scott Miller, EGLE  
Mr. Craig Dechy, EGLE